



CONSULTANTS GROUP

GEOLOGY

ENGINEERING

ENVIRONMENT

HYDROLOGY

April 19, 1988

RECEIVED
APR 19 1988

Mr. Lowell P. Braxton
Administrator,
Mined Land Reclamation Program
Utah Division of Oil Gas and Mining
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

DIVISION OF
OIL, GAS & MINING

Dear Mr. Braxton: *Lowell*

Enclosed please find copies of dump slope stability analysis reports prepared for the Barney Canyon Project by Sergeant Hauskins and Beckwith (SHB) and BP Minerals America (BPMA). The report by SHB is for the dump configuration originally submitted to DOGM in February and referenced in the Notice of Intent NOI). The report by BPMA is for the new dump configuration and is referenced in the recently submitted revision pages as an addendum to be provided.

Thank you very much.

Sincerely,

Robert J. Bayer
Vice President

cc: Mr. G. D. Schurtz, BP Minerals America
Mr. G. H. Boyce, Kennecott Explorations (Australia) Limited

Principal Office:
1841 East Fort Union Blvd.
Salt Lake City, Utah 84121
1-801-943-4144

Cedar City Office:
865 South Cedar Knolls West
Cedar City, Utah 84720
1-801-586-8793